

## Montage Acquisition

<b>Optique lowspec</b>	Zeiss 114mm	Zeiss 114mm	Zeiss 114mm	Thorlabs 80mm	Thorlabs 80mm	Thorlabs 80mm
<b>camera</b>	ZWO ASI 120	Moravian GX guider	APN	ZWO ASI 120	Moravian GX guider	APN
<b>T-Coulant male 1,25"</b>	X					X
<b>Coulant femelle 15mm</b>	X	X			X	
<b>Allonge T2 10mm</b>	Non		X			
<b>Allonge T2 15mm</b>	X					
<b>Allonge T2 20mm</b>	X			X		
<b>Allonge T2 45 mm</b>		X				
<b>Montage</b>	+++	+++	pas de vis/orient.	pas de vis/orient.	++	Out of focus
<b>Remarque</b>			IR/UV cut		camera enfoncée 50%	
<b>Champ CCD spectre</b>	--	--	+++	+	++	

## Montage Lowspec imageur

<b>Imager</b>	ED80	T200/1000
<b>SW Coulant femelle 1,25</b>		X
<b>Renvoi coudé</b>	Non	Non
<b>Barlow 3x</b>	Non	X
<b>Remarque</b>	montage direct	Barlow oblig

T300

à tester

PHD Guiding

## Guidage

ASI ZWO 120

ST4/ ST4 EQ6

Configurations recommandées

